

Firmware Change History for CW-C6000 series/CW-C6500 series

Version	Category	Detail
03.59.TS05JC	Added support model/OS	CW-C6500 series
03.59.TS26JC	Added new function	CW-C6000 series
	Changed function	Changed the timing of starting the suction fan and inserting of a label when inserting labels
		Changed the determination time to lock the carriage
		Changed the carriage return operation interrupted by an error opening the front cover during printing
Bug fix	Fixed a misdescription in the WebConfig	
03.59.TS19K2	Changed function	Changed a picture displayed on the LCD explaining how to remove paper jam
	Fixed bug	Fixed the remaining amount of ink displayed on the LCD during printing
		Corrected misdescription on the LCD
Fixed a bug occurred in the process to cancel jobs		
03.59.TS25K3	Changed function	Changed Peeler motor's control parameter
		Changed a misdescription on the LCD panel (WebConfig)
	Fixed bug	Fixed a misdescription on the LCD panel
		Fixed the message displayed on the LCD panel after an error is released
Fixed the masking area starting position for printing		
03.60.TS21K5	Changed function	To comply with the requirements of China's Energy Efficiency Label, changed respective default values for the followings: - Power consumption in the Sleep state - Timeout period to go into the Power saving mode Changed the Administrator lock function on the LCD panel
03.60.TS29K7	Added new function	Added the matte black ink
		Ink discharging function
		Enabled various settings using EpsonDeviceAdmin
		Displaying of remaining amount of paper in WebConfig
		Manual paper feeding
		Enhanced the compatibility with the Zebra printer
		Complied with the regulations (SB 327) in California, U.S.
	Reset of the Administrator lock password	
Changed function	Added the number of Read and Write function to cope with external I/O devices.	
Bug fix	Fixed a bug that a black square is printed in a specific area of one label during the continuous printing process.	
03.60.TS01K9	Bug fix	Fixed a bug below: If you leave the printer on without printing, the power is turned off automatically after 8 hours passes from the time when the power was turned on. * This symptom occurred only in the following specifications: - CW C6500Ae , CW C6500Pe - CW C6000Ae , CW C6000Pe
03.60.TS09KA	Function change	Changed the way to store data.
	Bug fix	Fixed a bug that the printer is initialized when using a mix of genuine and Fixed a bug that an error occurred communication between Epson Device
03.60.TS14L1	Updated support OS	Supported macOS Big Sur (11.0)
	Bug fix	Fixed error messages that are displayed via MIB (Management Information Base). Added "Clear error" to the stop condition for the continuous ringing
03.60.TS04L6	Updated support OS	End of support for the following OSes: - Windows XP SP3 (32bit) - Windows Server 2003SP2 (32bit) - Windows Server 2003 R2 SP2 (32/64bit) - Windows 11 (64bit) - Windows Server 2022 (64 bit)
	Bug fix	Fixed a calculation error that occurred in counting the life of Maintenance pump porous pad.
03.60.TS01LA	Updated support OS	Added support for the following OSes: -Windows 11 (64 bit) -Windows Server 2022
	Changed function	Improved the functionality for the following functions: 1)Paper width detection 2)Adjustment range of the print start position 3)External interface signals 4)Paper loading method 5)Abnormal noise that occurred at paper end
03.60.TS29LB	Changed function	Improved the functionality for the following functions: 1)Modified the acceleration of the peeler motor 2)Adjusted the timing of the detecting process of the Taken detector for the Peeler model