

Firmware Change History for TM-L90 (4** model/Standard)

Version	Category	Detail
3.07 ESC/POS	Changed function	Measures to prevent missing dots caused by Over energy.
	Fixed bug	Fixed a bug that QR codes/graphics are printed in mangled