

Firmware Change History for TM-P80 AC model

Version	Category	Detail
2.01 ESC/POS	Bug fix	While cutting the paper, it may detect cover open incorrectly so autocutter error is occurred.
2.21 ESC/POS	Updated support OS	End of support for the following OSes: -Windows 7 -Windows Vista
	New function	Added the Japanese specification.
	Function change	Dealt with the EOL of Flash ROM
		Improved the print quality
	Bug fix	Fixed a bug that Auto-PowerOFF does not work as specified
Fixed a bug that BM settings saved by the "GS (M" command are invalidated by the buffer clear command from TM utility		
Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control		
2.22 ESC/POS	Bug fix	Fixed a bug that the print density is low.