

Firmware Change History for TM-T20X Series

Version	Category	Detail
13.02 ESC/POS	Bug fix	Optimize the amount of the current from the CPU to the Ethernet transceiver.
13.04 ESC/POS	New function	Added Japanese fonts below: - JIS (JISX0208-1990): 6879 characters - Special characters: 845 characters (see below): - JIS : 2D21h to 2D7Eh, 7921h to 7C7Eh - JIS : 8740h to 879DEh, ED40h to EEFC, FA40 to FC4Eh
	Function change	Changed USB Device ID: MDL, CID
		Changed default password for WebConfig access from "epson" to the serial number of the printer to comply with the regulations (Chapter 886) in California, U.S.
		Changed contents of the self-signed certificate to comply with the iOS 13 specifications.
	Bug fix	Fixed a bug that a recovery point cannot be restored with the "Restore&Delete" operation.
Fixed a bug that the network response time slows down when a large amount of UDP packets is received at startup.		