

Firmware Change History for TM-T70II (180 dpi model)

Version	Category	Detail
5.05 ESC/POS	Function change	Applied countermeasures to prevent missing dots caused by Over energy.
	Bug fix	Fixed a bug that the printer is printing mangled QR codes or graphics when the receipt exceeds a certain size.
5.11 ESC/POS	Function change	Shortened the emission time of the paper real-end detector to prevent its deterioration.