

Firmware Change History for TM-T88VI-DT2

Version	Category	Detail
01.01 ESC/POS	Changed function	Change the offsets in the firmware to "none" in manufacturing process.
	Fixed bug	Fixed a bug that the printer error may occur after a specific Android device which is connected via USB restarted.
		Fixed a bug that the printer may not respond when repeatedly switching to/from the information acquisition mode.
		Fixed a bug that a watchdog timer error may occur when the printer repeatedly enters/leaves the power saving mode.
		Fixed a bug that the printer occasionally responded "Enable" to the host despite the USB flow control is disabled in the printer.
		Fixed a bug that a debugging error occurs if the printing and cutting operations are repeated in the Ethernet specification.
01.02 ESC/POS (New release)	Changed function	Improved printing speed in the low temperature and high density environment.