

## Firmware Change History for TM-T88VI

Version	Category	Detail
40.01 ESC/POS	-	New Release
40.02 ESC/POS	Added new function	TM-Intelligent function settings have been added to EpsonNet Config (Web version).
	Added new function	Added WebConfig API function.
	Fixed bug	Fixed a problem that the printer does not print after it has recovered from a paper out or roll paper cover open error while printing graphics from applications developed with Epson ePOS SDK for JavaScript or ePOS-Print XML.
		Fixed a problem that setting change using TM-T88VI Utility fails when the DNS server setting is set to Auto.
40.20 ESC/POS	Added new function	Setting of Bluetooth communication interval for power saving mode.
	Changed function	Changed status sheet button pressing time for status sheet print from 3 seconds to 1 second.
		Supported specific manufacturer drawer.
		Add TM-P80 to child printer.
	Fixed bug	Make it possible to obtain IP address from specific DHCP server (Cisco Switch: SG 500-29P).
		Fixed a problem that gateway address becomes "0.0.0.0" when LAN cable is removed / connected.
Fixed vulnerability of WPA2 (OT-WL05).		
40.21 ESC/POS	Added new function	Added the setting item for standby mode on the EpsonNet Config Web version.
	Fixed bug	Fixed a problem that network communication may become impossible when the link state of the network changed.
		Fixed a problem that network communication may become impossible when returning from the standby state.
		Fixed a problem that cannot print ePOS-Print via HTTPs.
40.22 ESC/POS	Added new function	Added a setting item of "Wellknown Community Name" on EpsonNet Config Web version.
	Changed function	Disabled "TLS1.0/1.1" for HTTPs in case of the "Encryption Strength" setting is set to "High".
		Changed to process ENPC 03-0021(status request) during power saving.
		Deleted "Wi-Fi" information from self-test printing.
	Fixed bug	Fixed Vulnerability of WPA2 (OT-WL02)
		Fixed Port 9100 connection may become impossible.
		Fixed LPR printing stops halfway.
		Fixed LPR printing may be delayed.
		Fixed that XML printing may become impossible.