

## Firmware Change History for TM-C3500 Series

Version	Category	Detail
WAM10200	Fixed bug	Fixed an issue that all LEDs (Status LED, Paper LED, and Ink LED) might flash momentarily after printer power-on.
WAM30200	Changed function	Changed the default setting of IP address in Network setting. -New: DHCP "Enable" (Old: DHCP "Disable" and Fixed IP address 192.168.192.168 ) -New: APIPA "Disable" (Old: APIPA "Enable" )
WAM31000	Added new function	Added the "Quality (Mode2)" mode to Print Quality.
		Added a setting to Paper Loading in the setting when the roll paper cover is closed.
		Added a function to extend the printable range of the lower end of the label by turning on the Dip switch 3.
	Changed function	Changed the amount of paper feeding until the media form error is detected.
		Changed the self-test printing regardless of paper form specified in the product.
		Changed the way of displaying an error name so as to scroll its name if an error in which its error code is displayed on the LCD.
Fixed bug	Fixed an issue that the final printing pass of the last sheet overlapped with the previous printing pass.	
WAM31100	Fixed bug	Fixed a bug that Web Config password is not saved.
WAM31200	Changed function	Changed the LCD message in the following languages since the intention in Japanese was not properly expressed: French, Italian, Portuguese, and Dutch
	Bug fix	Corrected spelling in the LCD message. (Dutch)
WAM31300	Changed function	Force reboot the printer approximately 5 times when a fatal error (B2) occurs. If this error occurs over 6 times in a row, the firmware treats it as a fatal error (B2).
WAM31400	New function	Added a function that supports a new impact sensor due to EOL of a current one.