

## Firmware Change History for TM-C3500 Series

| Version   | Category  | Detail   |
|-----------|---|--|
| WAM10200  | Fixed bug   | Fixed an issue that all LEDs (Status LED, Paper LED, and Ink LED) might flash momentarily after printer power-on.  |
| WAM30200  | Changed function  | Changed the default setting of IP address in Network setting.<br>-New: DHCP "Enable" (Old: DHCP "Disable" and Fixed IP address 192.168.192.168 )<br>-New: APIPA "Disable" (Old: APIPA "Enable" ) |
| WAM31000  | Added new function  | Added the "Quality (Mode2)" mode to Print Quality.   |
|           |   | Added a setting to Paper Loading in the setting when the roll paper cover is closed.   |
|           |   | Added a function to extend the printable range of the lower end of the label by turning on the Dip switch 3.   |
|           | Changed function  | Changed the amount of paper feeding until the media form error is detected.  |
|           |   | Changed the self-test printing regardless of paper form specified in the product.  |
|           |   | Changed the way of displaying an error name so as to scroll its name if an error in which its error code is displayed on the LCD.  |
| Fixed bug | Fixed an issue that the final printing pass of the last sheet overlapped with the previous printing pass. |  |
| WAM31100  | Fixed bug   | Fixed a bug that Web Config password is not saved.   |
| WAM31200  | Changed function  | Changed the LCD message in the following languages since the intention in Japanese was not properly expressed:<br>French, Italian, Portuguese, and Dutch   |
|           | Bug fix   | Corrected spelling in the LCD message. (Dutch)   |
| WAM31300  | Changed function  | Force reboot the printer approximately 5 times when a fatal error (B2) occurs. If this error occurs over 6 times in a row, the firmware treats it as a fatal error (B2).                         |