

Firmware Change History for TM-C7500 Series

| Version | Category | Detail |
|----------|--------------------|--|
| WAI20100 | Changed function | Added a function that displays the printing page count on LCD while printing. |
| WAI20300 | Fixed bug | Fixed an issue that printer sometimes does not work, displaying the LCD message 'Printer Error 62'. |
| WAI20500 | Fixed bug | Fixed an issue that displays 'paper jam error D1' when printer status is not occur paper jam. |
| | | Fixed an issue that printer sometimes does not work, displaying the LCD message 'Printer Error 62'. |
| WAI30000 | Added new function | Added a function for registering the print settings on a printer. You can select a registered print setting from "Menu" in the front panel. |
| | | Added a cleaning function to refill ink in the ink tube to "Menu" in the front panel.(Maintenance -> Ink Recharge) |
| WAI31000 | Added new function | Added a function that enables you to control pause ON/OFF by signal levels when using external I/F. |
| | Fixed bug | Fixed an issue that the active pause mode becomes disable after rebooting when using external I/F. |
| WAI31100 | Fixed bug | Fixed an issue that 'Paper Jam Error 61' is displayed when powering on the printer that is in any one of the following states: ("Ink Cartridge : Not set", "Maintenance Box : Not set", "Ink cartridge cover : Open", or "Maintenance box cover : Open") |
| WAI32000 | Added new function | Add a new command for CMYK image input. |
| | | Added a function to support a full-sized label (no black mark or no gap). |
| | Changed function | The function that cuts an incomplete label at the end of paper changed to selectable: to cut or not to cut. |
| | Fixed bug | Fixed the detecting logic for Media size error. |
| WAI32100 | Changed function | To reduce "ink splash" after the wiping, changed the wiping operation for each cleaning sequence. |
| | Fixed bug | Fixed an issue that 'Media Detection Error' that occurred at the time of use a full-sized label (no black mark or no gap). |
| | | Fixed an issue that blank paper will continue to be ejected for 30 seconds. |
| | | Fixed an issue that the black mark sensor adjustment value will be cleared when "Initialize media detection sensor" is selected from the panel menu under the following condition: * If the Media detect setting is set to "Media detect none". |
| WAI32200 | Fixed bug | To stabilize ink discharge, changed the control sequence for the print head driving circuit. |
| WAI32300 | Added new function | Enhanced security when updating the firmware. |
| WAI32400 | Added new function | Added the function of saving the main firmware version that worked last to EEPROM. |
| | Bug fix | Fixed a bug that no error is displayed even if a blowout of VHV fuse is detected during power-saving mode. Currently, the printer is paused when a fuse blows out (the printer stops running in the error state). |
| WAI32400 | Bug fix | Bug fix |
| WAI32600 | Changed function | Changed the LCD message in the following languages since the intention in Japanese was not properly expressed: French, Italian, Portuguese, and Dutch |
| | Bug fix | Corrected spelling in the LCD message. (Dutch) |
| WAI32700 | Changed function | Supported a new FlashROM device to deal with EOL of the current FlashROM. |
| | Updated support OS | Added support for the following OSes: -Windows 11 (64bit) -Windows Server 2022 (64 bit) |
| WAI33000 | Updated support OS | Added support for the following OSes: - Windows 11 - Windows Server 2022 - Windows Server 2019 - Windows Server 2016 End support for the following OSes: - Windows XP SP3 (32 bit) - Windows Server 2003 R2 SP2 (32bit) |
| | Changed function | Changed in specifications of the firmware associated with the change in main board. |
| | Bug fix | Fixed a bug that a black square is printed in a specific area of one label during the continuous printing process. |
| | Updated support OS | End support for the following OSes: - Windows 7 SP1 (32/64 bit) - Windows Vista SP2 (32/64 bit) - Windows Server 2008 SP2 (32/64 bit) - Windows Server 2008 R2 SP1 (64 bit) |
| WAI34200 | Changed function | The models have complied with the UK's PSTI bill. |
| | Bug fix | Fixed the vulnerability |
| WAI34300 | Bug fix | [Webconfig] Fixed a bug associated with initializing a password. |
| WAI34400 | Bug fix | Minor behavior fixes. |