

Firmware Change History for TM-T20II (**7 model)

Version	Category	Detail
10.10 ESC/POS	-	New Release
10.20 ESC/POS	Added new function	Support of Flash ROM W25Q64JVSSIM made by Winbond.
	Fixed bug	Fixed a problem in data reception flow control during USB communication.
		Fixed a problem that gateway address becomes "0.0.0.0" when LAN cable is removed / connected.
		Fixed a problem that Wi-Fi connection may not be possible when Wi-Fi security setting is set to enterprise.
		Fixed a problem that the firmware update fails rarely.
10.21 ESC/POS	Added new function	Added standby mode setting item on EpsonNet Config Web version.
	Fixed bug	Fixed a problem that network communication may become impossible when the link state of the network changed.
		Fixed a problem that network communication may become impossible when returning from the standby state.