

Firmware Change History for TM-T20II (**7 model)

Version	Category	Detail
10.10 ESC/POS	-	New Release
10.20 ESC/POS	Added new function	Support of Flash ROM W25Q64JVSSIM made by Winbond.
	Bug fix	Fixed a problem in data reception flow control during USB communication.
		Fixed a problem that gateway address becomes "0.0.0.0" when LAN cable is removed / connected.
		Fixed a problem that Wi-Fi connection may not be possible when Wi-Fi security setting is set to enterprise.
		Fixed a problem that the firmware update fails rarely.
10.21 ESC/POS	Added new function	Added standby mode setting item on EpsonNet Config Web version.
	Bug fix	Fixed a problem that network communication may become impossible when the link state of the network changed.
		Fixed a problem that network communication may become impossible when returning from the standby state.
10.22 ESC/POS	Added new function	Added setting item of "Wellknown Community Name" on EpsonNet Config Web version.
	Changed function	NOT support TLS1.0/1.1 for HTTPs, in case of "Encryption Strength" setting is set to "High".
		Changed to process ENPC 03-0021 during power saving.
	Bug fix	Fixed Vulnerability of WPA2(OT-WL02)
		Fixed Port 9100 connection may become impossible.
		Fixed LPR printing stops halfway.
	Fixed LPR printing may be delayed.	
10.24 ESC/POS	Bug fix	Fixed a bug that the printer error may occur after a specific Android tablet which is connected by USB restarted.
		Fixed a bug that cannot print after a timeout occurred in the ePOS-Print.