

Firmware Change History for TM-T20 (USB/Serial model)

Version	Category	Detail
1.21 ESC/POS	Changed function	Measures to prevent missing dots caused by Over energy.
	Bug fix	Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control.