

Firmware Change History

Drive	Version	Detail
PIONEER BDR-PR1EPDV	1.10	Corrected the following issue: The Drive internal error occurs when writing CDs, depending on PCs used in combination with the PP products.
	1.01	Corrected the following issue: The Writing error occurs in some CD-R media manufactured by Mitsubishi Chemical Media (including Verbatim brand).
PIONEER BDR-PR1EPA	1.10	Corrected the following issue: The Drive internal error occurs when writing CDs, depending on PCs used in combination with the PP products.
PIONEER BDW-PR1EPDV	1.01	Corrected the following issue: The Drive internal error occurs when writing Audio CDs, depending on PCs used in combination with the PP products.