

Firmware Change History for TM-P60II

Version	Category	Detail
5.31 ESC/POS	Function change	Improved the print quality
	Bug fix	Fixed a bug that BM settings saved by the "GS (M" command are invalidated by the buffer clear command from TM utility.
		Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control.