

## Firmware Change History for TM-P60II Peeler model

Version	Category	Detail
6.31 ESC/POS	Function change	Improved the print quality
	Bug fix	Fixed a bug that BM settings saved by the "GS ( M" command are invalidated by the buffer clear command from TM utility
		Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control