

Firmware Change History for TM-m30II

| Version                          | Category         | Detail  |
|----------------------------------|------------------|---|
| 02.03A ESC/POS<br>02.03B ESC/POS | New Release      | -   |
| 02.04A ESC/POS<br>02.04B ESC/POS | Changed function | Added "signature" and "serialNumber" parameters as an output parameter of GetLastTransactionResponse. This affects only the German Fiscal function.   |
|                                  | Bug fix          | Fixed a bug that there is a setting value that cannot be restored the recovery point with "Restore&Delete" in the panel operation.<br>(TM-m30II: Ver.02.03 ESC/POS)<br><br>Fixed a bug below:<br>In ePOS-Device, if one or more devices are connected to the printer, DEVICE_IN_USE is not resolved when returning the disconnect event from the client application immediately after executing createDevice. |
| 02.06A ESC/POS<br>02.06B ESC/POS | Bug fix          | Fixed a bug that the print position of image data printed in the page mode of the ePOS-SDK is out of alignment.   |
|                                  |                  | Fixed a bug that the Export function cannot be executed if TSE's certificate is expired. This affects only the German Fiscal function.  |
| 02.07A ESC/POS<br>02.07B ESC/POS | Bug fix          | Fixed a bug that ERROR_IO or SIG_ERROR may be returned from TSE. This affects only the German Fiscal function.  |
| 02.08A ESC/POS<br>02.08B ESC/POS | Function change  | Supported OT-WL06 in some regions (CIS, MEA)  |
|                                  | Bug fix          | Fixed a bug that unable to connect to WPA2 Enterprise APs using RADIUS servers that do not support TLS 1.0.   |
|                                  |                  | Fixed a bug that the page mode area and the line spacing are changed when specifying "mul" as the lang attribute to the text tag on ePOS-Print.   |
|                                  |                  | Fixed a bug that the ePOS-Device setting was disabled when the factory default recovery point was restored.   |

\* Ver.\*\*.\*\*B ESC/POS supports OT-WL05 and OT-WL06.

Firmware Change History for TM-m30II-H, TM-m30II-NT, and TM-m30II-S

| Version                          | Category              | Detail  |
|----------------------------------|-----------------------|---|
| 03.03A ESC/POS<br>03.03B ESC/POS | New Release           | -   |
| *Only for TM-m30II-H             |                       |   |
| 03.04A ESC/POS<br>03.04B ESC/POS | Changed function      | Added "signature" and "serialNumber" parameters as an output parameter of GetLastTransactionResponse. This affects only the German Fiscal function.   |
|                                  | Fixed bug             | Fixed a bug that there is a setting value that cannot be restored the recovery point with "Restore&Delete" in the panel operation.<br>(TM-m30II-H: Ver.03.03 ESC/POS)<br><br>Fixed a bug below:<br>In ePOS-Device, if one or more devices are connected to the printer, DEVICE_IN_USE is not resolved when returning the disconnect event from the client application immediately after executing createDevice. |
| 03.05A ESC/POS<br>03.05B ESC/POS | Updated support model | Supported TM-m30II-NT and TM-m30II-S.   |
|                                  | Fixed bug             | Fixed a bug that the setting values are cleared when unplugging the power cable about 25 seconds after the printer is turned on.  |

|                                  |                 |   |
|----------------------------------|-----------------|---|
| 03.06A ESC/POS<br>03.06B ESC/POS | Fixed bug       | Fixed a bug that the print position of image data printed in the page mode of the ePOS-SDK is out of alignment.<br><br>Fixed a bug that the Export function cannot be executed if TSE's certificate is expired. This affects only the German Fiscal function.   |
| 03.07A ESC/POS<br>03.07B ESC/POS | Fixed bug       | Fixed a bug that ERROR_IO or SIG_ERROR may be returned from TSE. This affects only the German Fiscal function.  |
| 03.08A ESC/POS<br>03.08B ESC/POS | Function change | Supported OT-WL06 in some regions (CIS, MEA)  |
|                                  | Bug fix         | Fixed a bug that unable to connect to WPA2 Enterprise APs using RADIUS servers that do not support TLS 1.0.<br><br>Fixed a bug that the page mode area and the line spacing are changed when specifying "mul" as the lang attribute to the text tag on ePOS-Print.<br><br>Fixed a bug that the cloud information cannot be got via WebConfig API. |

\* Ver.\*\*.\*\*A ESC/POS supports OT-WL02 and OT-WL06.

\* Ver.\*\*.\*\*B ESC/POS supports OT-WL05 and OT-WL06.